

## **Historic, archived document**

Do not assume content reflects current scientific knowledge, policies, or practices.



18  
N 22 X Res

# HOW MUCH **TURPENTINE** ARE YOU WASTING?

## **TO TURPENTINE OPERATORS:**

DO YOU realize how much turpentine you lose from uncovered dip barrels, in the woods and on the ramp, exposed to the sun on a long, hot day?

Do you realize how much turpentine you lose by having the turpentine hot when it comes from the worm into an uncovered separator?

You may be losing five gallons to every charge.

For every charge nearly \$2.50 worth of good turpentine goes off into the air.

## **YOU CAN EASILY PREVENT THESE LOSSES**

Keep dip barrels always covered with tight-fitting lids.

Put a roof over your ramp.

Be sure the worm is long and large enough.

Have plenty of **cold** water for cooling.

Keep the separator tightly covered.

## **PUT YOUR MONEY IN BANK, NOT IN THE AIR**

DO YOU WANT US TO SHOW YOU HOW?

WRITE TO

**U. S. DEPARTMENT OF AGRICULTURE**

NAVAL STORES INVESTIGATIONS

WASHINGTON, D. C.

